



EXAMPLE SHOWING TEMPLATE USE
 TO VERIFY 22.5 UP BY LINING UP THE CORNER
 OF THE INNER SQUARE BAR

NOTE: inner bar may be rotated clock wise
 5-7 degrees due to rubber taking a "set"